

CURVE-NO.6 B CONSTANT 25°C/50°C (K)-4038

NTC THERMISTOR R/T CONVERSION TABLE Rt/R25

TEMP.°C Rt/R25	TEMP.°C Rt/R25	TEMP.°C Rt/R25	TEMP.°C Rt/R25	TEMP.°C Rt/R25	TEMP.°C Rt/R25
-50=725000	-14=72700	22=11540	58=2598	94=765	130=277
-49=681700	-13=68940	23=11020	59=2499	95=741	131=270
-48=638400	-12=65190	24=10510	60=2400	96=720	132=264
-47=595000	-11=61430	* 25=10000	61=2320	97=699	133=257
-46=551700	-10=57670	26=9603	62=2240	98=678	134=250
-45=508400	-9=54910	27=9205	63=2161	99=657	135=244
-44=478900	-8=52150	28=8808	64=2081	100=637	136=238
-43=449400	-7=49400	29=8410	65=2001	101=619	137=232
-42=419900	-6=46640	30=8013	66=1936	102=602	138=227
-41=390400	-5=43880	31=7703	67=1871	103=584	139=221
-40=360900	-4=41830	32=7392	68=1807	104=567	140=215
-39=340600	-3=39780	33=7082	69=1742	105=549	141=210
-38=320200	-2=37730	34=6771	70=1677	106=535	142=206
-37=299900	-1=35680	35=6461	71=1624	107=520	143=201
-36=279500	0=33630	36=6217	72=1571	108=505	144=196
-35=259200	1=32100	37=5973	73=1518	109=490	145=191
-34=245000	2=30570	38=5729	74=1465	110=476	146=186
-33=230800	3=29050	39=5484	75=1412	111=463	147=182
-32=216600	4=27520	40=5241	76=1368	112=451	148=178
-31=202400	5=25990	41=5048	77=1325	113=438	149=174
-30=188200	6=24840	42=4855	78=1281	114=426	150=169
-29=178200	7=23690	43=4662	79=1238	115=413	
-28=168100	8=22540	44=4469	80=1194	116=403	
-27=158100	9=21390	45=4276	81=1158	117=392	
-26=148000	10=20240	46=4122	82=1122	118=382	
-25=138000	11=19370	47=3968	83=1086	119=371	
-24=130900	12=18500	48=3815	84=1050	120=361	
-23=123700	13=17630	49=3661	85=1014	121=352	
-22=116600	14=16760	50=3507	86=984	122=343	
-21=109400	15=15890	51=3384	87=954	123=334	
-20=102300	16=15220	52=3261	88=924	124=325	
-19=97130	17=14560	53=3138	89=895	125=316	
-18=91960	18=13890	54=3017	90=865	126=308	
-17=86800	19=13230	55=2894	91=840	127=300	
-16=81630	20=12560	56=2794	92=815	128=292	
-15=76460	21=12050	57=2696	93=790	129=285	